

REPORT OF SURVEY

Research of the records of Marion County revealed the following information:

ROADS: road on the 1/4 section line between the SE $\frac{1}{4}$ and the SW $\frac{1}{4}$ sec. 27, T 19S, R 1E opened as road # 142 $\frac{1}{2}$, 50 feet wide.

SURVEYS: Survey by K.D.O.T. for proj. 56-57-F062-2 (34) dated 1966 where the S.W. corner and the S 1/4 corner sec. 27 was recovered.
 Survey by Cutsinger LS 805 dated June 29, 1992 in the SE $\frac{1}{4}$ sec. 27 where Cutsinger recovered the Center Corner section 27.
 Survey by myself in the SW $\frac{1}{4}$ sec. 27 dated July 23, 1996 recorded Misc Bk. 184 at page 823 where I recovered the Center Corner, the S 1/4 corner, the S.W. corner and re-set the W 1/4 corner sec. 27 from Marion County witness ties.

FIELD PROCEDURE: I recovered the exterior corners of the SW $\frac{1}{4}$ sec. 27 from the surveys cited above, traversed the corners to determine their positions, and calculated a split of the SW $\frac{1}{4}$ into East and West halves, I then set out the 19.55 acre tract as directed by William Klassen by setting 1/2" rebar with I.D. caps as shown on the plat of survey, the rebar set at the N.E. corner and the S.E. corner of the tract was set 30.0 feet West of their true positions. The corner 564.31 feet North of the S.W. corner of the E $\frac{1}{2}$ of the SW $\frac{1}{4}$ fell 1.0 ft West of the West fence of two fences at this location. The corner 1670.29 ft South of the N.W. corner of the E $\frac{1}{2}$ of the SW $\frac{1}{4}$ fell 10.0 feet West of the Existing North-South fence.
 Nikon Total Station used to measure angles and distances.

WITNESS TIES TO CORNERS

Center Corner sec. 27, T 19S, R 1E
 found 1/2" rebar

In line with old fence to East
 5/8" rebar with I.D. cap 20.0 E
 T.W. North-South road 15.0 W
 S 1/4 corner sec. 27 2636.66 South

S 1/4 corner sec. 27, T 19S, R 1E
 found 5/8" rebar

center at East end R.C.P. 29.55 NW
 T.W. U.S. 56 Highway 34.5 S
 spike & washer in top cor. post 33.7 NE
 S.W. corner sec. 27 2659.8 West

S.W. corner sec. 27, T 19S, R 1E
 found 1/2" rebar

center at top 4"x4" conc. R/W marker 66.7 NNE
 center at top 4"x4" conc. R/W marker 76.7 NNW
 T.W. U.S. 56 Highway 20.0 South
 W 1/4 corner sec. 27 2642.44 North

W 1/4 corner sec. 27, T 19S, R 1E
 found 1/2" rebar with I.D. cap

Line of hedge to East 1.0 S
 Line of fence to South 19.6 W
 In center of N-S public road
 Center Corner sec. 27 2653.10 East